Release Date: March 5, 2021

VRMF Level Data Results:

VRMF level From:	89.11.33.0
VRMF Level To:	89.12.8.0
Report for:	DS8900F

Code Bundle Contents

DS8900F Code Bundle Level	SEA or LMC Version:		-	Storage Manager	Copy Services Manager
89.12.8.0	7.9.12.19	7.9.12.19	7.9.12.19	5.9.12.1006	6.2.10

Overview of new features and functions supported by this release on DS8900F 533x models 993/994/996

At a glance:

• Code fixes

This new microcode release supports DS8900F systems only.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1	High Impact	Acute: Irrecoverable error with potential loss of data.Serious: Irrecoverable error with potential loss of access to data, or critical function.	
2	Moderate	- A function not operational and/or performance might be degraded.	
3	Service	- A recoverable error (no impact) and service improvements.	
4	Improvements	- Improvement changes for better Usability and Serviceability.	

HIPER: High Impact problem that is Pervasive: 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

HIPER Potential DS8900F Data Loss during a system power outage

- 1. Problem Description: https://www.ibm.com/support/pages/node/6415607
- 2. Potential Impact of Problem: loss of data
- **3. Problem Severity:** HIPER
- 4. Pervasive Problem: No

ID# 350299

HIPER Timeouts and drive failures on Flash Drives with low usage

- 1. **Problem Description:** Certain specific Flash Drive models are exposed to conditions that may lead to a permanent read error when accessing data. https://www.ibm.com/support/pages/node/6414097
- 2. Potential Impact of Problem: loss of data
- 3. Problem Severity: HIPER
- 4. Pervasive Problem: No

ID# 352345

Potential SGC volume corruption

- 1. **Problem Description:** A timing window exists in DS8900F running R9.1 code, where SafeGuarded Copy and z/OS Space Release, or open system Unmap, may both update a volume metadata track at the same time. This will cause the affected SafeGuarded Copy volume to be unusable.
- 2. Potential Impact of Problem: loss of data
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 352850

SafeGuarded Copy volume stuck in Rolloff state

- 1. **Problem Description:** After an error recovery event during SGC Rolloff, SGC consistency group formation fails with "try later" sense.
- 2. Potential Impact of Problem: Loss of SafeGuarded Copy
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 353027

Serious: An irrecoverable error with potential loss of access to data, or critical function.

Removing volumes from an active XRC session may cause both clusters to reboot.

- 1. Problem Description: https://www.ibm.com/support/pages/node/6439821
- 2. Potential Impact of Problem: loss of access
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 350819

MGM session would not start after site swap

- **1. Problem Description:** Metro-Global-Mirror start H1-H2-H3 failed because of incorrect Out-of-Sync track bitmaps.
- 2. Potential Impact of Problem: Replication failure
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 351900

Moderate: A system path is not operational and/or performance may be degraded.

Warmstart during code update

- **1. Problem Description:** During FastPath CDA, LPAR quiesce collided with a background ODD dump process.
- 2. Potential Impact of Problem: Warmstart
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: No

ID# 351157

DS GUI/DSCLI CMUN00018E failure accessing HMC

- **1. Problem Description:** An ESSNI deadlock condition caused login token processing failures.
- 2. Potential Impact of Problem: HMC access failure
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: No

ID# 351973

0x7F0E MLE

- 1. **Problem Description:** A status field in a Data Mover task control block was updated after the task control block had been freed.
- 2. Potential Impact of Problem: Warmstart
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: No

ID# 352851

0x790E MLE when removing a SafeGuarded Copy volume

- **1. Problem Description:** When removing a fenced SGC volume, code is trying to update tables that no longer exist.
- 2. Potential Impact of Problem: Warmstart
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: No

ID# 352855

Service: A recoverable error, Service improvements.

Code bundle activation hang

- 1. **Problem Description:** A locking exception caused the code update process to hang while backing up HMC critical data.
- 2. Potential Impact of Problem: Extended service action
- 3. Problem Severity: Service
- 4. Pervasive Problem: No

ID# 351993

Security Key Lifecycle Manager configuration failure

- **1. Problem Description:** Key size error when adding a SKLM server that uses IBM Proprietary Protocol over TCP port 1441, or upgrading an existing IPP server to a version that uses port 1441.
- 2. Potential Impact of Problem: Unable to configure SKLM
- 3. Problem Severity: Service
- 4. Pervasive Problem: No

ID# 352152

Improvements: Improvements for better usability

None.

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered

trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to: IBM Director of Licensing

IBM Corporation North Castle Drive Armonk, NY 10504-1785 U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.